16/80 Rear Axle

Written by DouglasFox at May 28, 2008 12:17 pm

My 1934 16/80 is hors de combat with a broken half shaft and a graunched pinion gear. The crown wheel is undamaged. The diff ratio is 42:9.

Can anyone assist with advice on how best to rectify these problems, e.g. sources/availability of any replacement parts or modern substitutes that can be modified to fit?

Attachments:

Lag 16-80 Diff.jpg (filesize: 76.41 KB)

Lag 16-80 Half Shaft_1.jpg (filesize: 87.14 KB)

Lag 16-80 Half Shaft_2.jpg (filesize: 85.70 KB)