

Lagondaforum: Urgent cam follower question

Urgent cam follower question

Written by bruffsup at Feb 27, 2013 4:21 pm

The machine shop just called and discovered 2 of the lifters out of my M45 do not have holes. Can someone please advise. . Thanks, Barry Brown
