

## Lagondaforum: LG 45 rear nearside (left) Broken back plate

### LG 45 rear nearside (left) Broken back plate

*Written by bill at Dec 21, 2018 10:23 am*

Does anyone ,by any chance, have the remains of an LG45 rear nearside (left side) brake back plate that I could have please ? I need to repair the bottom half - only the bottom 4" or so. It is really only acting as a cover as there is nothing attached to it. It would be nice to use part of an original and do the job neatly rather than fabricating something. Therefore if someone had the remains of an original - which was no use for anything else - that would be brilliant. Any suggestions gratefully received.

Thanks.

---

### Re: LG 45 rear nearside (left) Broken back plate

*Written by bill at Dec 22, 2018 6:47 pm*

Since posting the above plea I realise of course that as I only need the bottom 3 and a half or 4 inches I could easily cut this out any rear back plate and maybe even out of the top bit or even a front back plate in fact. Does anyone have the remains of one which is of no use at all for anything else please ? All offers appreciated. Thanks.

---

### Re: LG 45 rear nearside (left) Broken back plate

*Written by Julian at Feb 27, 2019 3:54 pm*

Hi Bill,

You still in need?

Regards,  
Julian

---

### Re: LG 45 rear nearside (left) Broken back plate

*Written by bill at Mar 05, 2019 10:06 am*

Hi Julian

Thanks very much for the reply which I only just picked up.

Yes I am still looking - although I had resigned myself to fabricating something if necessary. Do you have the remains of something suitable ?

Thanks.

Bill